

萬里達車行(YAMAHA香港及澳門總代理) SMAX, MAJESTY S 及 FORCE

車型召回通知

有關召回詳情，請參閱以下列表

本公司將會跟受影響之本地及澳門（行貨）車主聯絡以預約時間回店更新零件

這次的召回通知 令FORCE, SMAX, MAJESTY S 之客戶帶來不便，敬請原諒！

（平行輸入俗稱水貨電單車將不獲得原廠免費之更換服務）

由於輪候需時，請耐心等待！

Man Lee Tat Car Company (YAMAHA Hong Kong & Macau Sole Distributor) Announcement for the Factory Modification Campaign of SMAX, MAJESTY S AND FORCE

Please refer to the table below for details of the modification

We will contact you for scheduling an appointment to return your FORCE, SMAX and MAJESTY S for FREE modification.

We feel deeply sorry for all the inconvenience caused.

(Parallel imported units will not be benefited from this campaign)

You may need to wait for booking schedule, thank you for your patience and understanding !

如閣下購買易手車後還沒有到本司更改車主資料，請帶備牌簿正本到本司更改資料，以便安排到更換服務

If you have brought the used motorcycle such as FORCE, SMAX & Majesty S, please bring along the original vehicle registration document to our company and to have the owner information change, so that we can schedule the modifying service booking to you

YAMAHA SMAX / FORCE

需更新零件 Replacement parts	汽缸蓋鎖付螺絲帽 CYLINDER HEAD NUTS
原因 Cause	部分螺絲帽的牙部形狀不佳，而影響鎖車時的摩擦力，可能導致鎖車時扭力不足 Due to an inappropriate tightening process of the cylinder head nuts, the axial varies widely. As a result, the sealing function of the cylinder head gasket was lost.
改正措施的內容 Remedy	全數免費更換汽缸蓋墊片及鎖付螺絲帽 Replace the Cylinder Gasket and Nut for free

